

#	ltem	Pg	Action	Projected
1	MASON. One or more sections of the exterior stairs are showing signs of deterioration. Recommend qualled masonry contractor evaluate & repair.	11	Repair and seal noted items as needed to prevent moisture intrusion.	\$545
			Sub-Total (Mason).	\$545
	CARPENTER/HANDYMAN.			
2	Front door has one panel that is cracked all the way through, recommend replacement by a qualied carpenter or handyman.	10	Replace and install exterior door.	\$375
	The decking boards at the edge of each entryway are loose and could present a tripping hazard, recommend these be repaired for		Service call to secure deck and fasteners.	\$139
	safety.			
4	Coat Closet door is missing a hinge pin which prevents it from working properly. Recommend repair to ensure proper operation and	21	Service doors as needed for smooth operation.	\$119
	prevent further damage.			
			Sub-Total (Carpenter/Handyman).	\$633
			Sub-rotal (Carpenter/Hamuyman).	9033
	ROOFING.			
5	Roof sheathing appears to be soft/thin in certain areas. This can be from decay in the underlying wood panels & structure.	8	Repair noted area to prevent water intrusion.	\$597
	Recommend further examination by a qualied roofer.			
6	Roof coverings exhibited general damage that could affect performance. Recommend a qualified roofer evaluate and repair. No active	13	Roof repairs needed in noted areas.	\$517
	leaks observed.			
			Sub-Total (Roofing).	\$1,114
			, 5,	
	WINDOW.			
7	Windows appear to be original to the home and many are in need of re-glazing. Recommend evaluation and repair by a window	21	Budget to replace windows.	\$2,210
	contractor.			
			Sub-Total (Window).	\$2,210
				,_, _,
	GUTTERS.			
8	There are no gutters on the back of the home. Without gutters all rainwater that runs o the roof will collect against the foundation,	15	Install gutters in locations noted.	\$746
	possibly causing foundation moisture problems and premature wood rot on the deck.			
			Sub-Total (Gutters).	\$746
			Jub Total (Jutters).	\$740